


Appendix B


Site Photographs




1. Exterior view of subject site facing southwest.



2. View of 3rd floor landscaped roof facing east.



3. View of rooftop penthouse exhaust metal casing with asbestos containing black caulking.




4. View of 3rd floor landscape roof flashing with asbestos containing grey caulking.



5. View of water damage in 3rd floor meeting room kitchen.



6. View of 3rd floor meeting room with asbestos containing vinyl floor tiles.



7. View of asbestos containing transite pipes.



8. View of mould on ceiling of 2nd floor parking garage.